

# Notification of LCD Repair Service Discontinuation

Issued December 2019

<b>Title</b>	<b>Notification of Repair Service being Discontinued for Air Leak Tester models FL-600 and FL-601</b>
--------------	---

To whom this may concern,

Thank you for your ongoing support.

This message is to provide notification that repair service of the LCDs of the long-running Air Leak Tester [Models FL-600 and FL-601] is being discontinued.

We thank you for your understanding and cooperation.

## 1. Models for which repair service is being discontinued

Product Names	Models
Air Leak Tester	FL-600, FL-601

\* Specifics: LCD repair service is being discontinued.

## 2. Repair service period

Final date of LCD repair service

December 10, 2019

Planned final date of repair service for other parts

End of March 2023

## 3. Reason for which repair service is being discontinued

- LCD repair of the FL-600 and FL-601 models is no longer possible as some parts are no longer obtainable.

## 4. Models for which repair service is being discontinued and replacement models

Model numbers for which LCD repair service is being discontinued	Replacement model numbers
FL-600, FL-601	FL-610, FL-611

\* Please contact the Overseas Sales Div. regarding replacement models.

## 5. Repair service

Repair service for other parts service will continue to be available.

Repair application period (planned): March 2023

\* Repair service for other parts may also be discontinued as parts inventory is exhausted.

## 6. Inquiries

### ◆Telephone inquiries

Overseas Sales Div.

Phone: +81-3-5848-7621

List of distributor contacts

<https://www.fukuda-jp.com/en/corporate/c04/>

### ◆Online inquiries

Contact form

English

<https://www.fukuda-jp.com/en/support/inquiry/>

\*Please begin your inquiry with "Re: FL-600 and FL-601 Sales Discontinuation."